

**SEARCH MODES**



**QUICK START**



This Getting Started Guide, the User Manual and translations are available to download online.



- EN English
- CZ čeština
- DE Deutsch
- EL ελληνικά
- HI हिन्दी
- ID Bahasa Indonesia
- IT Italiano
- JP 日本語
- KR 한국어
- PT Português
- RU русский
- TR Türkçe
- ZH 中文


[minelab.com](http://minelab.com)

# X-TERRA ELITE

GETTING STARTED GUIDE




## ASSEMBLY



## CHARGING

5-6 HOURS



**⚠** Charge your detector with a good-quality USB charger that has a minimum charging capacity of 2A @ 5V. Risk of USB charger failure if a low quality charger is used.

Look for the marks below on USB chargers.

## CONTROLS & DISPLAY

